

Cracking complex Naphtha and olefins



Please direct
questions to:
rc-cib@bbva.com

Basic Information

| | |
|--------------|----------------------------|
| Name | Cracking complex |
| Sector | Infrastructure |
| Country | Indonesia |
| Product | Corporate Related Loan |
| BBVA's role | MLA |
| Use of funds | Construction and operation |

Environmental and social management

| | |
|------------------------|----|
| E&S project category | B |
| E&S site category | B |
| E&S impact assessment | SI |
| E&S action plan | SI |
| E&S independent review | SI |

Definitions



Description

The project consists of the development, design, engineering, procurement, financing, construction, completion, testing, commissioning, ownership, operation and maintenance of a naphtha and olefins cracker, storage and utility infrastructure complex located in the Indonesian province of Banten.

Environmental and social impacts

| | |
|------------------------------------------|-------------------------|
| Expected emissions (tCO ₂ eq) | 60.5 M tCO _e |
| Employment creation (temporary) | 16.093 |

Disclaimer

This document has been drafted with an informative purpose. Banco Bilbao Vizcaya Argentaria, S.A., or any other of its Group companies (hereinafter 'BBVA') do not assume any obligation whatsoever to communicate any changes to this document or to update its contents. Notwithstanding the fact that reasonable measures to assure that the Information contained herein is not mistaken or misleading, BBVA does not represent or warrant, either express or implicit, its accuracy, integrity or correctness. BBVA accepts no liability of any type for any losses arising from the potential use of the document or its contents. This document is property of BBVA. Any denominations, designs, and logos are registered trademarks of BBVA. It is understood that its recipients accept all of the warnings and conditions contained herein in its integrity.